

**To:** CN=Steve Vandegrift/OU=ADA/O=USEPA/C=US@EPA[]  
**Cc:** bennett.shauna@epa.gov;perry.trina@epa.gov[]; erry.trina@epa.gov[]  
**From:** CN=Sujith Kumar/OU=ADA/O=USEPA/C=US  
**Sent:** Mon 7/23/2012 1:40:31 PM  
**Subject:** Re: Pavillion ADQ Phase V, Low MW acids

Steve:

Corrected reports will be reissued today.

Sujith Kumar  
Project Manager  
Shaw Environmental and Infrastructure  
US EPA RSKERC  
919 Kerr Research Drive  
P. O. Box 1198  
Ada, Oklahoma 74820  
580-436-8768 (Phone)  
580-436-8635 (Fax)

From: Steve Vandegrift/ADA/USEPA/US  
To: Sujith Kumar/ADA/USEPA/US@EPA  
Cc: Cindy Paul/ADA/USEPA/US@EPA, Rick Wilkin/ADA/USEPA/US@EPA, Shauna Bennett/ADA/USEPA/US@EPA, John Cox/ADA/USEPA/US@EPA  
Date: 07/20/2012 10:37 AM  
Subject: Pavillion ADQ Phase V, Low MW acids

Suji-

Another item identified in the Pavillion ADQ. Please have this issue checked and respond no later than Monday, 7/23.

Thanks,

Low MW Organic Acids. (a) The lab IDs appear to be wrong in the lab report for PGDW05-0412 (lab ID should be 6511-04, not 6507-4) and EPAMW01-0412-10 (lab ID should be 6521-14, not 6125-4).

Recommended Correction Action. (a) The lab IDs should be corrected as mentioned above in the final lab reports (note this does not affect final summary spreadsheet).

Steve Vandegrift, QA Manager  
Ground Water and Ecosystems Restoration Division  
NRMRL/ORD/USEPA  
P.O. Box 1198  
919 Kerr Research Dr.  
Ada, OK 74820  
(580)436-8684 (voice)  
(580)436-8528 (fax)

vandegrift.steve@epa.gov